

Location			Project			Hazard Type			Reference
Name	River Basin	District	Project Title	Report/Paper (Y/N)	Spatial information?	Flooding?	Landslide?	Steep Creek?	Citation
Goslin and L'Heureaux Creeks		RDFFG	Geotechnical Hazard Assessments for Goslin and L'Heureux Creeks	Y	Y		Y	Y	Piteau Associates. (November 1993). Geotechnical Hazard Assessments for Goslin and L'Heureux Creeks [Report]. Prepared for Ministry of Transportation and Highways.
McBride		RDFFG	Debris Flow Assessment Proposed Subdivision W1/2 D.L. 3307 McBride, BC	Y	Y			Y	Agra Earth & Environmental. (May 8, 1996). Debris Flow Assessment Proposed Subdivision W1/2 D.L. 3307 McBride, BC [Report].
McBride, Sunbeam Creek		RDFFG	Geotechnical Hazard Assessment Lot 2, DL 11662, Plan 9602 McBride, BC	Y			Y	Y	Agra Earth & Environmental. (January 30, 1998). Geotechnical Hazard Assessment Lot 2, DL 11662, Plan 9602 McBride, BC [Report].
Robson Valley	Fraser	RDFFG	Robson Valley Hazard Land Study Lamming Mills to Albreda, BC	Y	Y		Y	Y	BGC Engineering Inc. (January 28, 1999). Robson Valley Hazard Land Study Lamming Mills to Albreda, BC [Report]. Prepared for RDFFG.
Robson Valley		RDFFG	Hazard Assessment Highway 16 Spittal and Leona Creeks Robson District	Y				Y	Ministry of Highways (MoH). (March 1999). Hazard Assessment Highway 16 Spittal and Leona Creeks Robson District [Report]. Prepared for Ministry of Highways.
Highway 16 near Cardinal Ranch	Fraser	RDFFG	Landscape and Stream Hazard Assessment of Torrented Stream Above Cardinal Ranch	Y	Y			Y	Firth Hollin Resource Science Corporation. (May 7, 1999). Landscape and Stream Hazard Assessment of Torrented Stream Above Cardinal Ranch [Report].
Swift Creek (Valemount)	Fraser	RDFFG	Swift Creek Fan Hazard Assessment	Y	Y	Y	Y	Y	BGC Engineering Inc. (August 12, 1999). Swift Creek Fan Hazard Assessment [Report]. Prepared for Regional District of Fraser-Fort George
Rainbow Creek		RDFFG	Geotechnical Hazard Assessment Rainbow Creek Fan	Y	Y		Y	Y	AGRA Earth & Environmental Ltd. (January 25, 2000). Geotechnical Hazard Assessment Rainbow Creek Fan McBride, BC [Report]. Prepared for RDFFG.
Willox Creek		RDFFG	Survey and Terrain Modeling for Landscape Hazard Assessment Willox Creek, McBride, BC	Y			Y	Y	Firth Hollin Resource Science Corporation. (January 31, 2000). Survey and Terrain Modeling for Landscape Hazard Assessment Willox Creek, McBride, BC [Report]. Prepared for RDFFG.
Willox Creek		RDFFG	Willox Creek Emergency Geohazard Risk and Mitigation Assessment	Y	Y		Y	Y	BGC Engineering Inc. (October 30, 2020). Willox Creek Emergency Geohazard Risk and Mitigation Assessment [Report]. Prepared for RDFFG.
Swiftcurrent Creek (Mount Robson)		RDFFG	Swift Current Creek Fan – Geotechnical Hazard Assessment	Y	Y	Y	Y	Y	AGRA Earth & Environmental Ltd. (February 3, 2000). Geotechnical Hazard Assessment Swift Current Creek Fan [Report]. Prepared for RDFFG.
Packsaddle Creek		RDFFG	Terrain Stability Assessment Packsaddle Creek	Y			Y	Y	Firth Hollin Resource Science Corporation. (February 18, 2000). Terrain Stability Assessment Report – Frac. W ½ DL 7369 Cariboo District, Packsaddle Creek [Report].
Selkirk, Tapli, McKirdy, Snowcourse, Home creeks (Valemount)		RDFFG	Geotechnical Hazard Assessment Selkirk, Tapli, McKirdy, Snowcourse, and Home Creek	Y	Y		Y	Y	AMEC Earth & Environmental. (February 23, 2001). Geotechnical Hazard Assessment Selkirk, Tapli, McKirdy, Snowcourse, and Home Creek [Report]. Prepared for RDFFG.
Robson Valley		RDFFG	Stream Survey, Terrain Analysis and Landscape Hazard Assessments for 13 Creeks in the Robson Valley Area	Y	Y	Y	Y	Y	Firth Hollin Resource Science Corporation. (March 2002). Stream Survey, Terrain Analysis and Landscape Hazard Assessments for 13 Creeks in the Robson Valley Area of British Columbia [Report]. Prepared for RDFFG.
Saranna, Dulles, Collett creeks (Dunster)		RDFFG	Geotechnical Hazard Assessment Saranna, Dulles, and Collett Creeks Dunster, BC	Y	Y	Y	Y	Y	AMEC Earth & Environmental. (March 11, 2002). Geotechnical Hazard Assessment Saranna, Dulles, and Collett Creeks Dunster, BC [Report]. Prepared for RDFFG.
Wilson, D, Booth, Alder creeks (Dunster)		RDFFG	Geotechnical Hazard Assessment Wilson, D, Booth, and Alder Creeks Dunster, BC	Y	Y	Y	Y	Y	AMEC Earth & Environmental. (April 10, 2002).Geotechnical Hazard Assessment Wilson, D, Booth, and Alder Creeks Dunster, BC [Report]. Prepared for RDFFG.
Hagan and Gort Creeks (Dunster)		RDFFG	Geotechnical Hazard Assessment Hagan and Gort Creeks Dunster, BC	Y	Y	Y	Y	Y	AMEC Earth & Environmental. (April 19, 2002).Geotechnical Hazard Assessment Hagan and Gort Creeks Dunster, BC [Report]. Prepared for RDFFG.
Leona Creek (Robson Valley)		RDFFG	Detailed Geological Hazard Assessment Leona Creek Watershed	Y	Y		Y	Y	AMEC Earth & Environmental. (December 9, 2004).Detailed Geological Hazard Assessment Leona Creek Watershed Robson Valley [Report]. Prepared for RDFFG.
Leona Creek (Robson Valley)		RDFFG	Leona Creek Debris Flow Hazard Reconnaissance	Y	Y		Y	Y	AMEC Earth & Environmental. (June 21, 2012). Leona Creek Debris Flow Hazard Reconnaissance 13292 Bunbury Road, Robson Valley [Report]. Prepared for RDFFG.
Leona Creek (Robson Valley)		RDFFG	Leona Creek Debris Flow Hazard Supplementary Information	Y	Y			Y	AMEC Earth & Environmental. (August 14, 2012). Leona Creek Debris Flow Hazard 13292 Bunbury Road, Robson Valley Supplementary Information [Report]. Prepared for RDFFG.
Swiftcurrent Creek (Mount Robson)		RDFFG	Hydrotechnical Summary Report Swiftcurrent Creek	Y	Y	Y	Y	Y	DWB Consulting Services Ltd. (February 17, 2017). Hydrotechnical Summary Report Swiftcurrent Creek [Report].
Miworth and Prince George	Nechako	RDFFG	Nechako River Bank Erosion Study	Y	Y	Y			GeoNorth Engineering Ltd. (June 30, 1998). Nechako River Bank Erosion Study [Report]. Prepared for Ministry of Environment, Lands, and Parks.
Dore River	Dore	RDFFG	Hydrologic and Geomorphic Assessment of the Dore River	Y	Y	Y			McElhanney Ltd. (March 11, 2021). Hydrologic and Geomorphic Assessment of the Dore River [Report]. Prepared for RDFFG.
Various	Various	Various	Flooding and Landslide Events Southern British Columbia 1808-2006	Y	Y	Y	Y	Y	Septer, D. (2007). Flooding and Landslide Events Southern British Columbia 1808-2006. Prepared for Ministry of Environment.
McBride		RDFFG	A landslide in glacial lae clays in central British Columbia	Y	Y		Y		Thomson, S., & Mekechuk, J. (1982). A landslide in glacial lake clays in central British Columbia. Canadian Geotechnical Journal. 19(3): 296-306. https://doi.org/10.1139/t82-036
Robson Valley	Multiple	Multiple	The Robson Valley Story	Y		Y			Wheeler, M. J. (2008). <i>The Robson Valley Story: A Century of Dreams</i> . Sternwheeler Pres.
Valemount		RDFFG	Landslide Inventory Map of the Valemount Area. A detailed methodological description	Y	Y		Y		Bornaetxea, T., Blais-Stevens, A., & Miller, B. (2023). Landslide Inventory Map of the Valemount Area, British Columbia, Canada. A Detailed Methodological Description. In: Alcántara-Ayala, I., et al. Progress in Landslide Research and Technology, Volume 1 Issue 2, 2022. Progress in Landslide Research and Technology. Springer, Cham. https://doi.org/10.1007/978-3-031-18471-0_27
Various	Various	RDFFG	Historical DriveBC Events	N	Y	Y	Y	Y	DriveBC. (2022). Historical DriveBC Events 2006-2022 [Data]. Retrieved from https://catalogue.data.gov.bc.ca/dataset/historical-drivebc-events .
Various	Various	Various	An overview of recent large catastrophic landslides in Northern British Columbia	Y	Y		Y		Geertsema, M., Clague, J., Schwab, J. & Evans, S. (2006). An overview of recent large catastrophic landslides in Northern British Columbia, Canada. Engineering Geology. 83. 120-143. 10.1016/j.enggeo.2005.06.028 .